



West Nassau Landfill Closure

July 2011 through December
2012




Pre-Construction July 2011



West Nassau Landfill
7/09/2011

DAP Imaging, Inc.
904.964.9601

East Slope



South Slope



Access Road



East Slope



South Slope



August 2011

West Nassau Closure
8/7/2011

D&P Imaging, Inc.
904-994-8602

East Slope

Drilling New Wells



Relocating and Grading Waste



Installing Leveling Layer South Slope





November 2011

WEST NASSAU CLOSURE
11-15-2011
DAP IMAGING, INC.
904 994-8602

South Slope

Deploying Geomembrane





December 2011

East Slope

West Nassau Closure
12-13-2011

DAP Imaging
904-994-8602




February 2012

East Slope

West Nassau
2-18-2012

DAP Imaging, Inc
904 994-8602



Installing New Gas Lines South Slope



GFFR Installation East Slope





May 2012

East Slope


West Nassau
5/16/2012

DAP-Imaging, Inc.
904 994-8602

Tropical Storm Beryl

East Slope





Tropical Storm Beryl




North Slope

Tropical Storm Debby



East Slope



Tropical Storm Debby



North Slope

August 2012

East Slope



West Nassau
8-02-2012

DAP Imaging, Inc
904 994-8692

Installing Protective Cover North Slope



Sod Installation North Slope



October 2012 East Slope



West Nassau
1/20/12
DAP Imaging, Inc.
904.994.8800

GFFR Repair - South Slope





Substantial Completion

December 31, 2012

West Nassau
12/31/2012

DAP Imaging, Inc
904 994-8602

East Slope

South Slope



South Crossing



South GFFR



East GFFR



East Crossing



East Fence



**Access Road
& GFFR**



North Slope

